


2714 - Swivel nut branch tee


BSPP 60° Cone ends / BSPP 60° Female swivel end



Thread BSPP	Order code Steel	Parker cross reference Steel	Order code Stainless Steel	Parker cross reference Stainless Steel
1/8-28	2714-02-02	2S6MK4S	2714-02-02RVS	2S6MK4SS
1/4-19	2714-04-04	4S6MK4S	2714-04-04RVS	4S6MK4SS
3/8-19	2714-06-06	6S6MK4S	2714-06-06RVS	6S6MK4SS
1/2-14	2714-08-08	8S6MK4S	2714-08-08RVS	8S6MK4SS
5/8-14	2714-10-10	10S6MK4S	2714-10-10RVS	10S6MK4SS
3/4-14	2714-12-12	12S6MK4S	2714-12-12RVS	12S6MK4SS
1-11	2714-16-16	16S6MK4S	2714-16-16RVS	16S6MK4SS
1 1/4-11	2714-20-20	20S6MK4S	2714-20-20RVS	20S6MK4SS
1 1/2-11	2714-24-24	-	2714-24-24RVS	-
2-11	2714-32-32	-	2714-32-32RVS	-

2715 - Swivel nut run tee

BSPP 60° Cone ends / BSPP 60° Female swivel end



Thread BSPP	Order code Steel	Parker cross reference Steel	Order code Stainless Steel	Parker cross reference Stainless Steel
1/8-28	2715-02-02	2R6MK4S	2715-02-02RVS	2R6MK4SS
1/4-19	2715-04-04	4R6MK4S	2715-04-04RVS	4R6MK4SS
3/8-19	2715-06-06	6R6MK4S	2715-06-06RVS	6R6MK4SS
1/2-14	2715-08-08	8R6MK4S	2715-08-08RVS	8R6MK4SS
5/8-14	2715-10-10	10R6MK4S	2715-10-10RVS	10R6MK4SS
3/4-14	2715-12-12	12R6MK4S	2715-12-12RVS	12R6MK4SS
1-11	2715-16-16	16R6MK4S	2715-16-16RVS	16R6MK4SS
1 1/4-11	2715-20-20	20R6MK4S	2715-20-20RVS	20R6MK4SS
1 1/2-11	2715-24-24	-	2715-24-24RVS	-
2-11	2715-32-32	-	2715-32-32RVS	-